

Inventor: Miller et al.
For: Computer System with Bus Socket ...
Contact: Roger Fulghum/713-229-1707
Sheet 1 of 7




Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681

Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 2 of 7




Express Mail #EI754601912US
Filed: 02/28/01; File No. 016295.0681
Inventor: Miller et al.
For: Computer System with Bus Socket ...
Contact: Roger Fulghum/713-229-1707
Sheet 3 of 7



Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ...
Contact: Roger Fulghum/713-229-1707
Sheet 4 of 7







FIG 5


Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 5 of 7



Express Mail #EI754601912US Filed: 02/28/01; File No. 016295.0681 Inventor: Miller et al.


For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707 Sheet 6 of 7



Inventor: Miller et al.

For: Computer System with Bus Socket ... Contact: Roger Fulghum/713-229-1707

Sheet 7 of 7



900
DISPLAY
DRIVER
UNIT
DISPLAY

FIG. 9

Hardy than the four of the first wife